

Withdrawal/Termination CoC

CoC	Company Name	ISO System	Product	Brand	Model	Country of Origin	Load bearing	Stability	Integrity	Insulation	Standards	Test report	Assessment report	Date of Issue	Expiry Date		
10A001	Meng Leong Decoration	7	Fire Rated Swing Door (Metal)	MLSD series	MLSD series	Singapore	-	-	30	-	SS 332 : 2007 Clause 4	PSB ref. 54S060072/KKC (exclude Appendix 2 Item 1)	TUV SUD PSB ref. S08MEC03284/JC and S08MEC04458/IHN (exclude Clause 1.4a)	10/12/2013	09/12/2013		
10A002	Meng Leong Decoration	7	Fire Rated Swing Door (Metal)	MLSD series	MLSD series	Singapore	-	-	60	-	SS 332 : 2007 Clause 4	PSB ref. 54S060072/KKC (exclude Appendix 2 Item 1)	TUV SUD PSB ref. S08MEC03284/JC and S08MEC04458/IHN (exclude Clause 1.4a)	10/12/2013	09/12/2013		
10A003	Meng Leong Decoration	7	Fire Rated Swing Door (Metal)	MLSD series	MLSD series	Singapore	-	-	120	-	SS 332 : 2007 Clause 4	PSB ref. 54S060072/KKC (exclude Appendix 2 Item 1)	TUV SUD PSB ref. S08MEC03284/JC and S08MEC04458/IHN (exclude Clause 1.4a)	10/12/2013	09/12/2013		
10A004	Meng Leong Decoration	7	Fire Rated Swing Door (Metal)	MLSD series	MLSD series	Singapore	-	-	240	-	SS 332 : 2007 Clause 4	PSB ref. 54S060072/KKC (exclude Appendix 2 Item 1)	TUV SUD PSB ref. S08MEC03284/JC and S08MEC04458/IHN (exclude Clause 1.4a)	10/12/2013	09/12/2013		
11A008	Z1 Shutters Pte Ltd	7	Fire Rated Shutter	FUJIKAWA	-	Singapore	-	-	240	14	SS 489: 2001 Annex A & Clause 3.5	Exova Warringtonfire ref. 2538200.1	Exova Warringtonfire ref. 25371-00	08/03/2011	07/03/2014		
11A010	Schindler Lifts (Singapore) Pte Ltd	7	Fire Rated Lift Landing Door	Schindler	VARIDOR 30 ACP C2_3776	China	-	-	120	-	BS 476 Part 22 : 1987	BRANZ ref. FR 3776	BRANZ ref. FAR 3026 (exclude clause 4.15 & 5.15)	04/04/2011	03/04/2014		
11A011	Firespray International (Singapore) Pte Ltd	5	Fire Rated Duct System	Flamebar BW11	Flamebar BW11	United Kingdom	-	120	120	120	BS 476 Part 24 : 1987	LPC ref. TE82414, TE 82724, TE 84033, TE 87473 & WARRES ref. 44509	WF ref. 156568 Issue 2, BRE Assess ref. CC88343 Review 3 and CC89277A Review 3	11/05/2011	10/05/2017		
11A012	Pyronano Singapore	5	Fire Rated Swing Door (Glass)	Pyronano	EW-60/30	Singapore	-	-	60	30	SS 332 : 2007 Clause & BS 6206 : 1981	TUV SUD PSB ref. 719186905-MEC10-ST & 7191002179-MEC11-NLH	-	23/05/2011	22/05/2014		
11A013	Pyronano Singapore	5	Fire Rated Swing Door (Glass)	Pyronano	EI-60/60	Singapore	-	-	60	60	SS 332 : 2007 Clause & BS 6206 : 1981	Research Engineering Development ref. R09L20C and TUV SUD PSB ref. 719170830-MEC10-02-NLH	-	23/05/2011	22/05/2014		
11A014	Yi Qian Pte Ltd	7	Fire Rated Swing Door	DOLD	MFD-4	Singapore	-	-	240	-	SS 332 : 2007 Clause 4	TUV SUD PSB ref. 719185715-MEC10-IHN	-	11/05/2011	10/05/2014		
11A023	Inferno Global Pte Ltd	7	Fire Rated Sliding Door	FR Sliding	-	Singapore	-	-	60	60	SS 332 : 2007 Clause 4	BRANZ ref. FR 1085	BRANZ ref. FAR 1773 and FAR 2892	24/06/2011	23/06/2014		
11A024	Cheong Cheng Renovation & Carpentry Work	7	Fire Rated Swing Door	Pyrolink 60	-	Singapore	-	-	60	60	SS 332 : 2007 Clause 4	TUV SUD PSB ref. 54S072658/MW	TUV SUD PSB ref. 7191000734-MEC11-MW and BWA ref. 22112-06 (exclude A4.1.1 (xviii & xix), A4.2.9, A4.2.13, A4.2.14, A7.1.1 (viii))	28/06/2011	27/06/2014		
11A025	Cheong Cheng Renovation & Carpentry Work	7	Fire Rated Swing Door	Pyrolink 120	-	Singapore	-	-	120	120	SS 332 : 2007 Clause 4	TUV SUD PSB ref. S09MEC01910/IHN	BWA ref. 22112-06	28/06/2011	27/06/2014		
11A026	United Timber Pte Ltd	5	Fire Rated Swing Door	Pyrolink 60	-	Singapore	-	-	60	60	SS 332 : 2007 Clause 4	TUV SUD PSB ref. 54S072658/MW	TUV SUD PSB ref. 7191000734-MEC11-MW and BWA ref. 22112-06 (exclude A4.1.1 (xviii & xix), A4.2.9, A4.2.13, A4.2.14, A7.1.1 (viii))	28/06/2011	27/06/2014		
11A027	United Timber Pte Ltd	5	Fire Rated Swing Door	Pyrolink 120	-	Singapore	-	-	120	120	SS 332 : 2007 Clause 4	TUV SUD PSB ref. S09MEC01910/IHN	BWA ref. 22112-06	28/06/2011	27/06/2014		
11A027	Majesto Wood Enterprise	7	Fire Rated Swing Door	Pyrolink 120	-	Singapore	-	-	120	120	SS 332 : 2007 Clause 4	TUV SUD PSB ref. S09MEC01910/IHN	BWA ref. 22112-06	20/07/2011	19/07/2014		
11A028	Majesto Wood Enterprise	7	Fire Rated Swing Door	Pyrolink 60	-	Singapore	-	-	60	60	SS 332 : 2007 Clause 4	TUV SUD PSB ref. 54S072658/MW	TUV SUD PSB ref. 7191000734-MEC11-MW and BWA ref. 22112-06 (exclude A4.1.1 (xviii & xix), A4.2.9, A4.2.13, A4.2.14, A7.1.1 (viii))	20/07/2011	19/07/2014		
11A040	Promat Building System Pte Ltd	5	Protection to Structural Steel	VICUCLAD®	VD.00.24 Cladding	-	30 mins.	-	-	-	BS 476 Part 21 : 1987	WARRES ref. 25294, 29954/B, 26670, 27107, WRCSI ref. 25294-A-F, 25594B, BRE ref. TE 80908, TE 81093, TE 4017	WF ref. 152075 and BRE ref. CC84974 Review 3	01/10/2011	30/09/2014		
11A063	Inferno Global Pte Ltd	5	Fire Rated Swing Door	INNODOR 30	-	Singapore	-	-	30	30	SS 332 : 2007 Clause 4	TUV SUD PSB ref. 54S066128/ST	TUV SUD PSB ref. S08MEC05226/JC, 7191003747-MEC11-MW, 7191013744-MEC11-MW, 7191003747-MEC11-MW	22/08/2011	21/08/2014		
11A064	Inferno Global Pte Ltd	5	Fire Rated Swing Door	FERRODOR 120	-	Singapore	-	-	120	60	SS 332 : 2007 Clause 4	BRANZ ref. FR3970 & FAR3262	EWA ref. 26340-02	14/09/2011	13/09/2014		
11A066	Pyronano Singapore	5	Fire Rated Partition System (Glass)	PYRONANO	NANOFLAM EI 120/60	-	-	-	120	60	BS 476 Part 22 : 1987 & BS 6206 : 1981	RED ref. R09F17F	TUV SUD PSB ref. 719170830-MEC-02-NLH	13/10/2011	12/10/2014		
12A073	Inferno Global Pte Ltd	5	Fire Rated Swing Door	S63-HDD	-	Singapore	-	-	60	60	SS 332 : 2007 Clause 4	BRANZ ref. FR2485 & FAR1909	EWA ref. 26376-02	27/02/2012	26/02/2015		
12A075	OTIS Elevator Company (S) Pte Ltd	7	Fire Rated Lift Landing Door	OTIS ELEVATOR	2-PANEL CENTRE-OPENING WITH VISION PANEL	China	-	-	60	-	BS 476 Part 22 : 1987	TUV SUD PSB ref. S09MEC0101/KKC	TUV SUD PSB ref. S09MEC01496/JC	08/03/2012	07/03/2015		
12A079	Promat Building System Pte Ltd	5	Fire Rated Board System	VERMICULUX	INTUMEX-SS-240/240-VLX	-	-	-	-	-	BS 476 Part 21 : 1987	LPC ref. TE81979, TE82187, TE 82839 & TE82521	WFRAP ref. 184229	03/05/2012	03/05/2015		
13A0086	Rockwool Building Materials (Singapore) Pte Ltd	5	Fire Rated Duct System	CONLIT	Plus ALU	-	-	-	-	-	Refer to Appendix to CoC	Refer to Appendix to CoC	British Standard 476 Part 24 : 1987	TNO ref. 2004-CVB-R0047 (Rev. 1), 2004-CVB-R0048 (Rev. 1), 2004-CVB-R0049 (Rev. 1), 2004-CVB-R253 (Rev. 1)	EWA ref. 27559-02	15/02/2013	14/02/2016
13A0087	G & Y Trading & Manufacturing Pte Ltd	7	Fire Rated Swing Door	TMK	54S053252/KKC	Singapore	-	-	60	60	SS 332 : 2007 Clause 4	PSB ref. 54S053252/KKC and	TUV SUD PSB ref. 7191002297-MEC11-MW & 7191005057-MEC11/01-JC, WFRAP ref. 21774-02, EWA ref. 22679-04	22/02/2013	21/02/2016		
13A0088	G & Y Trading & Manufacturing Pte Ltd	7	Fire Rated Swing Door	RICSHERR	54S03219/ST	Singapore	-	-	30	30	SS 332 : 2007 Clause 4	PSB ref. 54S03219/ST	TUV SUD PSB ref. 7191005057-MEC11/02-JC & 7191006592-MEC11-JC, WFRAP ref. 002800.2, WFRAP ref. 21811-01, EWA ref. 21303-05 & 24211-00	22/02/2013	21/02/2016		
12A089	Promat Building System Pte Ltd	5	Fire Rated Partition System	PROMAVIC	PMV.23.60, PMV.23.120 & PMV.80.12	-	-	-	-	-	Refer to Appendix to CoC	Refer to Appendix to CoC	British Standard 476 Part 22 : 1987	LPC ref. TE86523, FIRTO ref. TE3333, WARRES ref. 58347	BRE ref. CC88481 Rev.3 & CC252273	03/05/2013	02/05/2016
13A0090	Unicorn International Pte Ltd	7	Fire Rated Swing Door (Metal)	ARMORTEX	CUSTOMISED	USA	-	-	60	30	SS 332 : 2007 Clause 4	TUV SUD PSB ref. 7191055021-MEC13-ST	-	11/06/2013	10/06/2016		